#### Caring Leadership

Changing a safety culture 2014 PPSA Safety and Health Conference

Mike Hignett

Wakefield, Ma. Corrugated Facility-RockTenn

#### Old school: < 10 recordables was considered "good"

#### From 2002 to 2008

- Averaged one recordable per year
- All safety training, policies, programs in place
- Managed safety through my direct reports to the floor
- Life was good until I hit "the summer of 2009" ....



## 'Summer of 2009'

4 recordables in 45 days!

## Stop the madness!

How do I do this?

Two avenues to choose from.

One choice was .....



# THE BEATINGS WILL CONTINUE



UNIL SAFETY MPROVES

## Begin a full court press

- Direct report meetings and a 'personal note' from me.
- Full scale safety reviews with all the tools available to me
  - Safety awareness videos and action plans
  - "Break the plane" and "Hands Up!"
  - Supervisory weekly audits became daily

The "madness" stopped but something was missing.

I knew I did NOT have a true safety culture.

Was it luck all those years?



# Look at myself – Was I the problem? Was I truly committed to running a safe plant?

- Begin the change >
- Did NOT go through direct reports to the get message to the floor

   go myself all 3 shifts.
- Started talking one on one with employees all 3 shifts
- Began two safety teams in order to cover three shifts
- Sought out employee concerns and made them my 'Daily Hot List'

Communicate Communicate



Forktruck speed




▶ Fork truck with lite bar and spot



Pedestrian Safety







	EMPLOYEE ENGAGEMENT ACTIVITIES		
1	Safety team member	26	Safety Bingo - run it for one month
2	Incident investigation team - ONE YEAR	27	MSDS AUDIT - 5 chemicals at a time
3	Machine Safety Audit	28	Emergency lighting checks
4	Area Dept. Safety Audit	29	Emergency evacuation map audit - departmental
5	Machine Guarding Audit	30	Complete any one of the Safety Compliance Handbook audits
6	Plant wide Inspection	31	Assist with any Salcon audit finding correction
7	Conduct a Safety meeting or Toolbox meeting	32	Check Incident Investigation kit - up to date, everything there
8	Complete PIT Checklist audit	33	Check "Redbook" to see if up to date (Emergency Procedures)
9	Tell a Safe Start story in the safety meeting	34	Ladder Inspection
10	Electrical Safety Audit	35	Trailer audit - wheel chocks in place, glad locks, trailer jacks
11	Do a lockout audit and document it	36	Assist with or complete a HazRac audit
12	Review SWPs and suggest updates	37	Write safety orientation for front lobby DVD
13	Housekeeping Team	38	Conduct safety training - one topic
14	Complete a departmental combustible dust audit	39	Conduct steam leak audit
15	Assist with or conduct a DuPont STOP audit	40	Maintenance employee to audit contractor safety: PPE, walkways, etc
16	Conduct 10 "Hands Up" audits	41	Organize and run outside BBQ
17	Complete an Electrical Safety audit	42	Report NEAR MISSES & CLOSE CALLS
18	Home made tools search - departmental	43	Develop employee recognition awards
19	Secondary Container labeling audit - departmental	44	Ceiling leak check and record findings (when it is raining)
20	Write safety slogans for the message light by time clock (5 MINIMUM)	45	Shipping dock check - docklocks, bumpers, lights
21	Eyewash inspections	46	Hand power tool inspection
22	Fire Extinguisher monthly checks	47	Hydraulic jack inspection
23	Organize safety poster contest	48	Slings, chains, straps, cable inspection
24	Air hose / hose clamp / nozzle inspection - departmental	49	Two man lift stickers on die boards
25	Slip / trip-hazard-insepction - departmental	50	Pre-shift machine center inspections

Open Employee Engagement Log as of 4/30/14 - Updated Status as of 5/8/14

Total hazards reported through Employee Engagement activities: 62


Total new hazards reported since 4/30/14: 0

Total reported hazards open at 4/30/14: 35 Total reported hazards open as of 5/8/14: 15

Company	Area	Machine	Reported By	Audit Date	Deviation	Nork Order #	Issue Date	Status	Closed Date	Comments		
CR   1021   LS   4/19/2014   Floor grates   1/48963   4/19/2014   Closed   CloSED   Change gear box												
CR   1021   BK, SD   4/25/2014   Roll movers   115/3029   4/25/2014   Closed   CLOSED   Change Batteries more frequently	CR	1021	BK, JF, AO, LS	3/13/2014	Fix guard on	1108410	3/17/2014	Closed	CLOSED	Guard fixed		
CR   Boler   JB   4/19/2014   Red wire exg   1150097   4/19/2014   Open   Change geor box	CR	1021	LS	4/19/2014	Floor grates	1148963	4/19/2014	Open		Need new concrete around edges of pit- Harnam		
CR	CR	1021	BK, SD	4/25/2014	Roll movers	1153029	4/25/2014	Closed	CLOSED	Change Batteries more frequently		
CR	CR	Baler	JB	4/19/2014	Red wire exp	1150097	4/19/2014	Open				
CR	CR	Baler	JB	4/19/2014	Oil leak fron	1150101	4/19/2014	Open		Change gear box		
CR	CR	Palletizer	JG, RB	3/6/2014	Install missir	1096901	3/6/2014	Closed	CLOSED	Nothing missing		
Area   Machine   Reported By   Audit Date   Deviation   Work Order   Issue Date   Status   Closed Date   Comments	CR	Palletizer	JG, RB	3/6/2014	Replace/inst	1096904	3/6/2014	Closed	CLOSED	Nothing found missing		
Area	CR	Starch	JF, BK	4/19/2014	Storage tani	1148956	4/22/2014	Open				
CV         4561         EV         3/13/2014         Electrical imp         1104692         3/13/2014         Closed         5/8/2014         Addressed on scheduled PM           CV         4561         EG, VS, JT         3/14/2014         Replace/inst         1105458         3/14/2014         Closed         CLOSED         Missing roll Piers were replaced           CV         4561         KN         4/19/2014         Missing roll 1145958         4/19/2014         Closed         5/8/2014         Addressed on scheduled PM           CV         4561         KN         4/19/2014         Hoist belt is         1145959         4/19/2014         Closed         5/8/2014         Maderssed on scheduled PM           CV         4561         KN         4/19/2014         Hoist belt is         1145959         4/19/2014         Closed         5/6/2014         Addressed on scheduled PM           CV         4562         AG         3/12/2014         On main cor         100413         3/13/2014         Closed         5/6/2014         Addressed on scheduled PM           CV         4562         AG         3/12/2014         On main cor         100419         Missing roll of the missi	Converting											
CV 4561 E6, VS, JT 3/14/2014 Replace/ins 1105458 3/14/2014 Closed 5/8/2014 Addressed on scheduled PM  CV 4561 KN 4/19/2014 Hots bet is 1145959 4/19/2014 Closed 5/8/2014 Starp was replaced  CV 4561 KN 4/19/2014 Hots bet is 1145959 4/19/2014 Closed 5/8/2014 Starp was replaced  CV 4561 KN 4/19/2014 Exposed wir 1145950 4/19/2014 Closed 5/8/2014 Addressed on scheduled PM  CV 4562 A6 3/12/2014 Pomenin cor 1104713 3/13/2014 Closed 5/8/2014 Addressed on scheduled PM  CV 4562 IR, LV 3/13/2014 Fix source of 1105442 3/13/2014 Closed 5/6/2014 Machine center does not provide for them  CV 4562 SA 4/18/2014 Operator's 1145954 4/18/2014 Closed 5/6/2014 Tightened fitting  CV 4562 SA 4/18/2014 Operator's 1145954 4/18/2014 Closed 5/6/2014 Clos	Area	Machine	Reported By	Audit Date	Deviation	Nork Order #	Issue Date	Status	Closed Date	Comments		
CV 4561 KN 4/19/2014 Holst belt is 1145958 4/19/2014 Closed 5/6/2014 Strap was replaced  CV 4561 KN 4/19/2014 Exposed wir 1145950 4/19/2014 Closed 5/6/2014 Addressed on scheduled PM  CV 4561 KN 4/19/2014 Exposed wir 1145960 4/19/2014 Closed 5/6/2014 Addressed on scheduled PM  CV 4562 AG 3/12/2014 On main cor 1104713 3/13/2014 Closed 5/6/2014 Machine center does not provide for them  CV 4562 IR, IV 3/13/2014 Fix source of 1105442 3/13/2014 Closed 5/6/2014 Machine center does not provide for them  CV 4562 SA 4/18/2014 Operator's s 1145482 4/18/2014 Open  CV 4562 SA 4/18/2014 Operator's s 1145482 4/18/2014 Open  CV 4563 MP, MR 3/13/2014 Cover expos 1105455 3/13/2014 Closed 5/6/2014 Nothing found exposed  CV 4563 PP, AA, MI 4/16/2014 Missing at 1142317 4/16/2014 Open  CV 4563 IR, IR 4/18/2014 Conveyor or 114536 4/18/2014 Open  CV 4563 IR, IR 4/18/2014 Conveyor or 114536 4/18/2014 Open  CV 4563 HB 4/25/2014 Conveyor or 1153347 4/25/2014 Open  CV 4561 TD, DW 2/25/2014 Replace from 1086695 2/26/2014 Open  CV 4571 TD, DW 2/25/2014 Replace from 1086695 2/26/2014 Open  CV 4571 TD, DW 2/25/2014 Replace from 1086698 2/26/2014 Closed 5/6/2014 After review, guards were not installed -deemed it would create pinch per CV 4571 AX 4/16/2014 Open Missing 2 pt 1142315 4/16/2014 Closed 5/6/2014 Corrected on 5/6/14 scheudled PM  CV 4571 TD, DW 4/19/2014 Open Missing 2 pt 1145955 4/18/2014 Open CV 4571 AX 4/16/2014 Open Missing 2 pt 1145955 4/18/2014 Open CV 4571 AX 4/16/2014 Open Missing 2 pt 1145955 4/18/2014 Open Missing 2 pt 114595 4/18/2014 Open Missing 2 pt 1145955 4/1	CV	4561	LV	3/13/2014	Electrical inp	1104692	3/13/2014	Closed	5/8/2014	Addressed on scheduled PM		
CV 4561 KN 4/19/2014 Hoist belt is 1145959 4/19/2014 Closed 5/6/2014 Strap was replaced CV 4561 KN 4/19/2014 Exposed win 1145960 4/19/2014 Closed 5/6/2014 Machine center does not provide for them CV 4562 AG 3/12/2014 On main or. 1104713 3/13/2014 Closed 5/6/2014 Machine center does not provide for them CV 4562 IR, LV 3/13/2014 Fix source of 1105442 3/13/2014 Closed 5/6/2014 Tightened fitting CV 4562 SA 4/18/2014 Open CV 4562 SA 4/18/2014 Open SAGE SA 4/18/2014 Open CV 4563 MP, MR 3/13/2014 Closed 5/6/2014 Closed 5/6/2014 Nothing found exposed CV 4563 MP, MR 3/13/2014 Closed 5/6/2014 Nothing found exposed CV 4563 PR, AA, MI 4/16/2014 Missing gu at 143594 4/16/2014 Open Scheduled for next PM due on 5/15/14 CV 4563 IR, IR 4/18/2014 Closed 5/6/2014 Closed 5/6/2014 Nothing found exposed CV 4563 IR, IR 4/18/2014 Closed 5/6/2014 Closed 5/6/2014 Nothing found exposed CV 4563 IR, IR 4/18/2014 Closed 5/6/2014 Closed 5/6/2014 Nothing found exposed CV 4563 IR, IR 4/18/2014 Closed 5/6/2014 Open Scheduled for next PM due on 5/15/14 CV 4563 IR 4/18/2014 Replace fray 1086697 2/26/2014 Open Scheduled for next PM due on 5/15/14 CV 4571 TD, DW 2/25/2014 Replace fray 1086697 2/26/2014 Open Scheduled for next PM due on 5/15/14 CV 4571 IP, MP, LS 3/14/2014 Permanenti, 1105454 3/14/2014 Closed 5/6/2014 Nothing found missing CV 4571 AX 4/16/2014 Permanenti, 1105454 3/14/2014 Closed 5/6/2014 Nothing found missing CV 4571 AX 4/16/2014 Open Missing 2 pt 1145955 4/19/2014 Closed 5/6/2014 C	cv	4561	EG, VS, JT	3/14/2014	Replace/inst	1105458	3/14/2014	Closed	CLOSED	Missing rollers were replaced		
CV 4561 KN 4/19/2014 Exposed wir 1145960 4/19/2014 Closed 5/8/2014 Addressed on scheduled PM  CV 4562 R, LV 3/13/2014 Fix ourse of 1104713 3/13/2014 Closed 5/6/2014 Machine center does not provide for them  CV 4562 R, LV 3/13/2014 Fix ourse of 1105442 3/13/2014 Closed 5/6/2014 Tiple med fitting  CV 4562 S, AP, AM, H 4/16/2014 Oil leak (driv. 1142310 4/16/2014 Open  CV 4562 SA 4/18/2014 Operator's s 1145482 4/18/2014 Closed 5/6/2014 Closed 5/6	cv	4561	KN	4/19/2014	Missing roll	1145958	4/19/2014	Closed	5/8/2014	Addressed on scheduled PM		
CV 4562 IR, LV 3/13/2014 Fix source of 1054713 3/13/2014 Closed 5/6/2014 Tightened fitting  CV 4562 IR, LV 3/13/2014 Fix source of 105482 3/13/2014 Closed 5/6/2014 Tightened fitting  CV 4562 SA 4/18/2014 Operator's s 1145342 4/18/2014 Operator's s	CV	4561	KN	4/19/2014	Hoist belt is:	1145959	4/19/2014	Closed	5/6/2014	Strap was replaced		
CV 4562   IR, LV 3/13/2014   Fix source of 1105442   3/13/2014   Closed   5/6/2014   Tightened fitting   CV 4562   SA A/18/2014   Operator's   1145482   4/16/2014   Operator's   CV 4562   SA 4/18/2014   Missing 2 to 1145946   4/19/2014   Operator's   CV 4563   SA 4/18/2014   Missing 2 to 1145946   4/19/2014   Operator's   CV 4563   PR, AA, MJ 4/16/2014   Missing guo   1142317   4/16/2014   Closed   5/6/2014   Nothing found exposed   CV 4563   PR, AA, MJ 4/16/2014   Missing guo   1142317   4/16/2014   Closed   5/6/2014   Operator's   CV 4563   IR, JR 4/18/2014   Conveyor pri   1153347   4/25/2014   Operator's   CV 4563   HB 4/25/2014   Conveyor pri   1153347   4/25/2014   Operator's   CV 4571   TD, DW 2/25/2014   Replace fray   1086695   2/26/2014   Operator's   CV 4571   TD, DW 2/25/2014   Replace pina   1086697   2/26/2014   Closed   S/6/2014   Operator's   CV 4571   IP, MP, LS 3/14/2014   Replace/instell guare   1086697   2/26/2014   Closed   S/6/2014   Operator's   CV 4571   IP, MP, LS 3/14/2014   Replace/instell guare   1086697   Closed   S/6/2014   Closed   S/6/2014   Operator's   CV 4571   IP, MP, LS 3/14/2014   Replace/instell guare   1086697   Closed   S/6/2014   Closed   S/6/2014   Operator's   CV 4571   IP, MP, LS 3/14/2014   Replace/instell guare   1086697   Closed   S/6/2014   Closed   S/6/2014   Operator's   CV 4571   AX 4/16/2014   Operator's   1142313   A/16/2014   Closed   S/6/2014   Operator's   CV 4571   AX 4/16/2014   Operator's   1142313   A/16/2014   Closed   S/6/2014   Operator's   CV 4571   SX 4/19/2014   Signage for   1145995   A/19/2014   Closed   S/6/2014   Closed   S/6/201	CV	4561	KN	4/19/2014	Exposed wire	1145960	4/19/2014	Closed	5/8/2014	Addressed on scheduled PM		
CV 4562	CV	4562	AG	3/12/2014	On main con	1104713	3/13/2014	Closed	5/6/2014	Machine center does not provide for them		
CV 4562 SA 4/18/2014 Operator's s 1145482 4/18/2014 Closed 5/6/2014 Chain replaced  CV 4562 SA 4/18/2014 Missing 2 ro 1145946 4/19/2014 Open  CV 4563 MP, MR 3/13/2014 Cover expos 1105455 3/13/2014 Closed 5/6/2014 Nothing found exposed  CV 4563 PR, AA, MJ 4/16/2014 Missing gua 1142317 4/16/2014 Closed 5/6/2014 Replaced guard  CV 4563 IR, JR 4/18/2014 Conveyor an 1145546 4/18/2014 Open Scheduled for next PM due on 5/15/14  CV 4563 HB 4/25/2014 Conveyor an 1145346 4/18/2014 Open Scheduled for next PM due on 5/15/14  CV 4571 TD, DW 2/25/2014 Replace fray 1086697 2/26/2014 Open Scheduled for next PM due on 5/15/14  CV 4571 TD, DW 2/25/2014 Replace fray 1086697 2/26/2014 Open Scheduled for next PM due on 5/15/14  CV 4571 TD, DW 2/25/2014 Replace fray 1086697 2/26/2014 Open Scheduled for next PM due on 5/15/14  CV 4571 TD, DW 2/25/2014 Replace fray 1086697 2/26/2014 Open Scheduled for next PM due on 5/15/14  CV 4571 TD, DW 2/25/2014 Replace/ins 1086697 2/26/2014 Open Scheduled for next PM due on 5/15/14  CV 4571 IP, MP, LS 3/14/2014 Replace/ins 1105452 3/14/2014 Closed 5/6/2014 After review, guards were not installed -deemed it would create pinch potential formation of the scheduled PM Missing 2 pl 1145915 4/16/2014 Closed Scheduled Scheduled PM Scheduled PM Scheduled PM Scheduled PM Missing 2 pl 1145915 4/19/2014 Closed Scheduled Scheduled PM Scheduled PM Scheduled PM Scheduled PM Missing 2 pl 1145915 4/19/2014 Closed Scheduled Scheduled PM Scheduled PM Scheduled PM Scheduled PM Missing 2 pl 1145915 4/19/2014 Closed Scheduled PM Sch	cv	4562	IR, LV	3/13/2014	Fix source of	1105442	3/13/2014	Closed	5/6/2014	Tightened fitting		
CV 4562 SA 4/18/2014 Missing 2 ro 1145946 4/19/2014 Open  CV 4563 MP, MR 3/13/2014 Cover expos 1105455 3/13/2014 Closed 5/6/2014 Nothing found exposed  CV 4563 PR, AA, MI 4/16/2014 Missing gua 1142317 4/16/2014 Closed 5/6/2014 Replaced guard  CV 4563 IR, IR 4/18/2014 Conveyor an 1145546 4/18/2014 Open Scheduled for next PM due on 5/15/14  CV 4563 HB 4/25/2014 Conveyor an 1145546 4/18/2014 Open Scheduled for next PM due on 5/15/14  CV 4563 HB 4/25/2014 Replace fray 1086695 2/26/2014 Open Scheduled for next PM due on 5/15/14  CV 4571 TD, DW 2/25/2014 Replace fray 1086695 2/26/2014 Open Scheduled for next PM due on 5/15/14  CV 4571 TD, DW 2/25/2014 Replace pine 1086697 2/26/2014 Open Scheduled for next PM due on 5/15/14  CV 4571 IP, MP, LS 3/14/2014 Replace pine 1086698 2/26/2014 Closed 5/6/2014 After review, guards were not installed -deemed it would create pinch potential to the state of th	cv	4562	, AP, AM, H	4/16/2014	Oil leak (driv	1142310	4/16/2014	Open				
CV 4563 MP, MR 3/13/2014 Cover expos 1105455 3/13/2014 Closed 5/6/2014 Nothing found exposed  CV 4563 PR, AA, MJ 4/16/2014 Missing gue 1142317 4/16/2014 Closed 5/6/2014 Replaced guard  CV 4563 IR, JR 4/18/2014 Conveyor an 1145546 4/18/2014 Open Scheduled for next PM due on 5/15/14  CV 4563 HB 4/25/2014 Conveyor pr 1153347 4/25/2014 Open Scheduled for next PM due on 5/15/14  CV 4571 TD, DW 2/25/2014 Replace fray 1086695 2/26/2014 Open Scheduled for next PM due on 5/15/14  CV 4571 TD, DW 2/25/2014 Replace fray 1086697 2/26/2014 Open Scheduled for next PM due on 5/15/14  CV 4571 TD, DW 2/25/2014 Replace pin 1086697 2/26/2014 Open Scheduled for next PM due on 5/15/14  CV 4571 TD, DW 2/25/2014 Replace pin 1086697 2/26/2014 Open Scheduled for next PM due on 5/15/14  CV 4571 IP, MP, LS 3/14/2014 Replace pin 1086698 2/26/2014 Closed 5/6/2014 After review, guards were not installed -deemed it would create pinch pot 5/6/2014 Nothing found missing Sing CV 4571 IP, MP, LS 3/14/2014 Permanenth 105454 3/14/2014 Closed 5/6/2014 Corrected on 5/6/14 scheudled PM  CV 4571 AX 4/16/2014 One missing 1142315 4/16/2014 Closed 5/6/2014 Corrected on 5/6/14 scheudled PM  CV 4571 TD, DW 4/19/2014 Die cut press 1142323 4/16/2014 Open CV 4571 TD, DW 4/19/2014 Signage for 1142595 4/19/2014 Closed 5/6/2014 Replaced missing rollers  CV 4571 SS 4/19/2014 Replace/inst 995392 ######### Open CV 7999 RG, AN 3/13/2014 Replace/inst 995392 ########## Open CV 7999 MC, PK, AX 4/19/2014 Before strap 1145994 4/19/2014 Open CV 7999 MC, PK, AX 4/19/2014 Before strap 1145994 4/19/2014 Open CV 7999 MC, PK, AX 4/19/2014 Before strap 1145994 4/19/2014 Open CV 7999 MC, PK, AX 4/19/2014 Before strap 1145994 4/19/2014 Open CV 7999 MC, PK, AX 4/19/2014 Before strap 1145994 4/19/2014 Open CV 7999 MC, PK, AX 4/19/2014 Before strap 1145994 4/19/2014 Open CV 7999 MC, PK, AX 4/19/2014 Before strap 1145994 4/19/2014 Open CV 7999 MC, PK, AX 4/19/2014 Before strap 1145994 4/19/2014 Open CV 7999 MC, PK, AX 4/19/2014 Before strap 1145994 4/19/2014 Open CV 7999 MC, PK, AX 4/	cv	4562	SA	4/18/2014	Operator's s	1145482	4/18/2014	Closed	5/6/2014	Chain replaced		
CV 4563 PR, AA, MJ 4/16/2014 Missing gua 1142317 4/16/2014 Closed 5/6/2014 Replaced guard  CV 4563 IR, JR 4/18/2014 Conveyor an 1145546 4/18/2014 Open Scheduled for next PM due on 5/15/14  CV 4563 HB 4/25/2014 Conveyor pr. 1153347 4/25/2014 Open Scheduled for next PM due on 5/15/14  CV 4571 TD, DW 2/25/2014 Replace fray 1086695 2/26/2014 Open Scheduled for next PM due on 5/15/14  CV 4571 TD, DW 2/25/2014 Replace pine 1086695 2/26/2014 Open Scheduled for next PM due on 5/15/14  CV 4571 TD, DW 2/25/2014 Install guara 1086698 2/26/2014 Closed 5/6/2014 After review, guards were not installed -deemed it would create pinch potentially contained by the contained by th	cv	4562	SA	4/18/2014	Missing 2 ro	1145946	4/19/2014	Open				
CV 4563 IR, JR 4/18/2014 Conveyor an 1145546 4/18/2014 Open Scheduled for next PM due on 5/15/14  CV 4563 HB 4/25/2014 Conveyor pr 1153347 4/25/2014 Open Scheduled for next PM due on 5/15/14  CV 4571 TD, DW 2/25/2014 Replace fray 1086695 2/26/2014 Open  CV 4571 TD, DW 2/25/2014 Replace pine 1086697 2/26/2014 Open  CV 4571 TD, DW 2/25/2014 Replace pine 1086697 2/26/2014 Open  CV 4571 TD, DW 2/25/2014 Install guar 1086698 2/26/2014 Closed 5/6/2014 After review, guards were not installed -deemed it would create pinch por CV 4571 IP, MP, LS 3/14/2014 Replace/inst 1105452 3/14/2014 Closed 5/6/2014 Nothing found missing  CV 4571 IP, MP, LS 3/14/2014 Permanenth 1105454 3/14/2014 Closed 5/6/2014 Corrected on 5/6/14 scheudled PM  CV 4571 AX 4/16/2014 One missing 1142315 4/16/2014 Closed 5/6/2014 Corrected on 5/6/14 scheudled PM  CV 4571 TD, DW 4/19/2014 Missing 2 pl 1145955 4/19/2014 Closed 5/6/2014 Guards were not replaced as previously existing guards created a pinch process of the street	CV	4563	MP, MR	3/13/2014	Cover expos	1105455	3/13/2014	Closed	5/6/2014	Nothing found exposed		
CV 4563 HB 4/25/2014 Conveyor pr 1153347 4/25/2014 Open Scheduled for next PM due on 5/15/14  CV 4571 TD, DW 2/25/2014 Replace fray 1086695 2/26/2014 Open CV 4571 TD, DW 2/25/2014 Replace pinc 1086697 2/26/2014 Open CV 4571 TD, DW 2/25/2014 Install guard 1086698 2/26/2014 Closed 5/6/2014 After review, guards were not installed -deemed it would create pinch potentially contained by the contained	cv	4563	PR, AA, MJ	4/16/2014	Missing gua	1142317	4/16/2014	Closed	5/6/2014	Replaced guard		
CV 4571 TD, DW 2/25/2014 Replace fray 1086695 2/26/2014 Open  CV 4571 TD, DW 2/25/2014 Replace pind 1086697 2/26/2014 Open  CV 4571 TD, DW 2/25/2014 Install guard 1086698 2/26/2014 Closed 5/6/2014 After review, guards were not installed -deemed it would create pinch per company of the compa	cv	4563	IR, JR	4/18/2014	Conveyor an	1145546	4/18/2014	Open		Scheduled for next PM due on 5/15/14		
CV 4571 TD, DW 2/25/2014 Replace pind 1086697 2/26/2014 Open  CV 4571 TD, DW 2/25/2014 Install guard 1086698 2/26/2014 Closed 5/6/2014 After review, guards were not installed -deemed it would create pinch potentially contained by the contained	cv	4563	HB	4/25/2014	Conveyor pr	1153347	4/25/2014	Open		Scheduled for next PM due on 5/15/14		
CV 4571 TD, DW 2/25/2014 Install guard 1086698 2/26/2014 Closed 5/6/2014 After review, guards were not installed -deemed it would create pinch policy of the control of the	cv	4571	TD, DW	2/25/2014	Replace fray	1086695	2/26/2014	Open				
CV 4571 IP, MP, LS 3/14/2014 Replace/insi 1105452 3/14/2014 Closed 5/6/2014 Nothing found missing  CV 4571 IP, MP, LS 3/14/2014 Permanenth, 1105454 3/14/2014 Closed 5/6/2014 Corrected on 5/6/14 scheudled PM  CV 4571 AX 4/16/2014 One missing 1142315 4/16/2014 Closed 5/6/2014 Corrected on 5/6/14 scheudled PM  CV 4571 AX 4/16/2014 Die cut press 1142323 4/16/2014 Open  CV 4571 TD, DW 4/19/2014 Missing 2 pl 1145955 4/19/2014 Closed 5/6/2014 Guards were not replaced as previously existing guards created a pinch process of the composition of the	cv	4571	TD, DW	2/25/2014	Replace pind	1086697	2/26/2014	Open				
CV 4571 IP, MP, LS 3/14/2014 Permanenth, 1105454 3/14/2014 Closed 5/6/2014 Corrected on 5/6/14 scheudled PM  CV 4571 AX 4/16/2014 One missing 1142315 4/16/2014 Closed 5/6/2014 Corrected on 5/6/14 scheudled PM  CV 4571 AX 4/16/2014 Die cut press 1142323 4/16/2014 Open  CV 4571 TD, DW 4/19/2014 Missing 2 pl 1145955 4/19/2014 Closed 5/6/2014 Guards were not replaced as previously existing guards created a pinch process of the control of the	cv	4571	TD, DW	2/25/2014	Install guard	1086698	2/26/2014	Closed	5/6/2014	After review, guards were not installed -deemed it would create pinch point		
CV 4571 AX 4/16/2014 One missing 1142315 4/16/2014 Closed 5/6/2014 Corrected on 5/6/14 scheudled PM  CV 4571 AX 4/16/2014 Die cut press 1142323 4/16/2014 Open  CV 4571 TD, DW 4/19/2014 Missing 2 pl 1145955 4/19/2014 Closed 5/6/2014 Guards were not replaced as previously existing guards created a pinch process of the company of the com	CV	4571	IP, MP, LS	3/14/2014	Replace/inst	1105452	3/14/2014	Closed	5/6/2014	Nothing found missing		
CV 4571 AX 4/16/2014 Die cut press 1142323 4/16/2014 Open  CV 4571 TD, DW 4/19/2014 Missing 2 pl. 1145955 4/19/2014 Closed 5/6/2014 Guards were not replaced as previously existing guards created a pinch process. CV 4571 SS 4/19/2014 Signage for 1145997 4/19/2014 Closed 5/6/2014 Replaced missing rollers  CV 7999 RG, AN 3/13/2014 Replace/inst 995392 ######### Open  CV 7999 MC, PK, AX 4/19/2014 Before strap 1145994 4/19/2014 Open	cv	4571	IP, MP, LS	3/14/2014	Permanently	1105454	3/14/2014	Closed	5/6/2014	Corrected on 5/6/14 scheudled PM		
CV         4571         TD, DW         4/19/2014         Missing 2 pl         1145955         4/19/2014         Closed         5/6/2014         Guards were not replaced as previously existing guards created a pinch pl           CV         4571         SS         4/19/2014         Signage for 1145997         4/19/2014         Closed Closed Closed Closed S/6/2014         Feplaced missing rollers           CV         7999         RG, AN RG, AN RG, AN AM	cv	4571	AX	4/16/2014	One missing	1142315	4/16/2014	Closed	5/6/2014	Corrected on 5/6/14 scheudled PM		
CV         4571         SS         4/19/2014         Signage for l145997         4/19/2014         Closed Closed Closed Closed Signage for l145997         5/6/2014         Replaced missing rollers           CV         7999         RG, AN 3/13/2014         Replace/inst 995392         #########         Open         Open           CV         7999         MC, PK, AX 4/19/2014         Before strap 1145994         4/19/2014         Open	cv	4571	AX	4/16/2014	Die cut press	1142323	4/16/2014	Open				
CV 7999 RG, AN 3/13/2014 Replace/inst 995392 ######## Open CV 7999 MC, PK, AX 4/19/2014 Before strap 1145994 4/19/2014 Open	cv	4571	TD, DW	4/19/2014	Missing 2 ple	1145955	4/19/2014	Closed	5/6/2014	Guards were not replaced as previously existing guards created a pinch point		
CV 7999 MC, PK, AX 4/19/2014 Before strap 1145994 4/19/2014 Open	cv	4571	SS	4/19/2014	Signage for	1145997	4/19/2014	Closed	5/6/2014	Replaced missing rollers		
	CV	7999	RG, AN	3/13/2014	Replace/inst	995392	########	Open				
	CV	7999	MC, PK, AX	4/19/2014	Before strap	1145994	4/19/2014	Open				
CV 7999 DG 4/24/2014 Missing doo 1156635 4/29/2014 Open	cv	7999	DG	4/24/2014	Missing doo	1156635	4/29/2014	Open				
CV 7999 CS 4/18/2014 Exposed or c 1156639 4/29/2014 Open	ćv	7999	cs	4/18/2014	Exposed or d	1156639	4/29/2014	Open				



#### May Employee Engagement



WE MADE IT !!!



Glove Type Characteristic

Glove Type





























Has Armer\* 9" Ann Guard Cut and Puncture Resistant Arm Puncture Resistant Resistant Arm Puncture Resistant Resistan





▶ Thanks for your attention.

Stay Safe!

